F-02ED0389

FIG. 1A




FIG. 1B





FIG. 1C



Customer NO.: 23995

F-02ED0389

2/12

FIG. 2D




FIG. 2E





FIG. 2F



Atty Docket: OKI 398 Customer NO.: 23995 3/12

F-02ED0389

FIG. 3A




FIG. 3B





FIG. 3C



F-02ED0389

4/12

FIG. 4D




FIG. 4E





FIG. 4F



Customer NO.: 23995

F-02ED0389

FIG. 5A




FIG. 5B





FIG. 5C



F-02ED0389

FIG. 6D




FIG. 6E





FIG. 6F



Customer NO.: 23995

F-02ED0389

7/12

FIG. 7A




FIG. 7B





FIG. 7C



F-02ED0389

FIG. 8D




FIG. 8E





FIG. 8F



Customer NO.: 23995 9/12

F-02ED0389

FIG. 9A **PRIOR ART**




FIG. 9B **PRIOR ART**





FIG. 9C **PRIOR ART**



F-02ED0389

FIG. 10D PRIOR ART





FIG. 10E PRIOR ART



Customer NO.: 23995 11/12

F-02ED0389

FIG. 11A **PRIOR ART**




FIG. 11B **PRIOR ART**





FIG. 11C **PRIOR ART**



Atty Docket: OKI 398 Cust mer NO.: 23995

F-02ED0389

FIG. 12D PRIOR ART




FIG. 12E PRIOR ART




FIG. 12F PRIOR ART

